Applies To: **1998–01 Accord** **November 14, 2008**

Product Update: 1998–01 Accord 8-Way Power Driver's Seat

(Supersedes 03-034, dated September 2, 2003, to update the information marked by the black bar)

This Product Update campaign has ended. Any repair cost is now the customer's responsibility.

© 2008 American Honda Motor Co., Inc. – All Rights Reserved

Skill Level R REPAIR

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.